FIELD INSPECTION REPORT

ate of I	nspection: 02	12/20	District: Banka		
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	HARLEY BEEN HOLD FOR		Length (km): 1,476	ol khund.	
ame of	the Road: Charte	MERALA NOWN	Cashbur Road - BASTICO VIA K	COLBUJYPA	
while the last wife	TO THE POST OF THE PARTY OF THE	MAINTENANCE	D IIINO AIGO CO CO	M. Verger States	
	No.: RMIBALL	3AN/19/0010	Road Id No.: NEA 2200030	<u>y</u>	
the set in	atus of the Project: Ongoing/Completed/Under ork is a case of: New Connectivity/Up grad		In gradation/ Maintenance	fation/ Mainfenance	
SI. No.	a case of:	3.海水(加速率加速增速点水火火)。1.4.1.4.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1	Falca Union 13 m 2 m 2 m 2 m 2 m 2 m 2 m 2 m 2 m 2 m	Remarks	
		Parameters to	NDCCTCCCC		
	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U S/U S/U S/U	
d)	Road Camber			S/U	
e)		Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any Yes/N			Yes/No	
2.	Cross Drainag	e			
a)	Condition of he	Condition of head walls in Hume pipe culverts including its painting S/SI			
b)	Condition of A	Condition of Abutment & Wing walls, Slab in RCC culverts S/8			
c)		ilings/slab/approac	h for Bridges	S/SRI/U S/SRI/U S/SRI/U	
3.11	Road Furnitu	re			
a)			y/cautionary Board/km & 200m re provided and maintained	Yes/No	
4.	Compliance F	listory			
a)	Status of ATR	's & any others		जिल्हा स्वायतम् इसेन्यु व हे हे हैं दे वे के हिंदू हैं।	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: DHARMVEER KUMAR

DESIGNATION: JE