

NAME: *Surinder Kumar*
S.D.O
R.W.D. Chakrabarty

Surinder
02/10/20

Satisfactory (S)	N.A
Satisfactory but requires Improvement (SRI)	N.A
Unsatisfactory (U)	N.A

Overall Rating :

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	Work not started
a)	Road Junction condition	N.A
b)	Condition of Surfacing	N.A
c)	Riding Quality	N.A
d)	Road Camber	N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
f)	Construction joints provided or not (CC Pavement)	N.A
g)	Compaction of Bank/slope & raincurb if any	N.A
2.	Cross Drainage	N.A
a)	Condition of head walls in Raine pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railing/slab approach for bridges	N.A
3.	Road Furniture	N.A
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Work not started
4.	Compliance History	Work not started
a)	Status of ATR's & any others	

Date of Inspection : 03-12-2020	District : Subul	Length (km) : 2.950 km	Name of the Road : <i>Udgaonpur to Baganpur Pur Road</i>	Scheme Programme : MAINTENANCE	Package No. : Road Id No. :	Status of the Project : (Ingoing/Completed/Under Maintenance)	Work is a case of: New Connectivity/Up gradation/ Maintenance
---------------------------------	------------------	------------------------	--	--------------------------------	-----------------------------	---	---