

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Sargolpur
Division : Rosea		Length (km): 1.730 Km
Name of the Road: About Bank more to Motipur via About		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance completed	
Work is a case of:	New Connectivity/Up gradation/ Maintenance maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N.A.	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Some potland patches developed need to repair immediately *IPH* 03/12/2020
J-E, Rosea-1

IPH 03/12/2020
(Signature) J-E, Rosea-1

NAME: DENDAYAL CHOUHAN

DESIGNATION: J-E / Rosea, R.W.D.