

# FIELD INSPECTION REPORT

Date of Inspection : 08/11/2020		District: Purnea
Division : Baisi		Length (km): 2.100 KM
Name of the Road: Terdahi to Parasrai		
Scheme/Programme:	MAINTENANCE (MR 3054)	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U <u>NA</u>
b)	Condition of Surfacing	S/U <u>NA</u>
c)	Riding Quality	S/U <u>NA</u>
d)	Road Camber	S/U <u>NA</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>NA</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>NA</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No <u>NA</u>
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>NA</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <u>NA</u>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>NA</u>
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	-NA- (recently started)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*Harsh Kumar*  
(Signature) 08/11/2020

NAME: Gaurav Kumar

DESIGNATION: ASSISTANT ENGINEER