

FIELD INSPECTION REPORT

Date: 08/12/2022	District: Chapra (Bihar)
Road: Bhabhauri - Pharpur	Length (km): 3.233
Programme: MAINTENANCE	Road Id No.: 3054 M/R
Project: Ongoing/Completed/Under Maintenance	Activity not started
Type of: New Connectivity/Up gradation/ Maintenance	3054 M/R

Parameters to be checked	Remarks
Pavement	
1. Junction condition	S/U
2. Condition of Surfacing	S/U
3. Compacting Quality	S/U
4. Camber	S/U
5. Pavement free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
6. Expansion Joints provided or not (CC Pavement)	Yes/No
7. Protection of flank/slope & raincuts if any	Yes/No
Bridges & Drainage	
1. Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
2. Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
3. Condition of railings/slab/approach for Bridges	S/SRI/U
Furniture	
1. Directional sign boards/informatory/cautionary Board/km & 200m /Pavement road markings are provided and maintained	Yes/No ✓
Maintenance History	
1. Details of ATR's & any others	✓

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

6662
08/12/2022

(Signature)