

FIELD INSPECTION REPORT

Inspection : 08/12/2020	District: Chapra (Saran)
Chapra-3	Length (km): 1.532
of the Road: Rampatti - 5 m. p.m.	
Programme: MAINTENANCE	30/11/12
No.:	Road Id No.:
of the Project:	Ongoing/Completed/Under Maintenance other work Activity not checked
a case of:	New Connectivity/Up gradation/ Maintenance 30/11/12

Parameters to be checked	Remarks
Pavement	
Road Junction condition	S/U
Condition of Surfacing	S/U
Riding Quality	S/U
Road Camber	S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Contraction Joints provided or not (CC Pavement)	Yes/No
Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
Compliance History	
Status of ATR's & any others	

Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

616
08/12/2020

(Signature)