

FIELD INSPECTION REPORT

Date of Inspection : 9/12/20		District: E. Champasak
Division : Raxaul		Length (km): 5.20 km
Name of the Road: Cont. of Road from Trienay muih to MA-BA Bhuwra Chowk via Puenhthi		
Scheme/Programme: MAINTENANCE		MR-3054 (New maintenance Policy)
Package No.: RM/EA/RA/20/0009		Road Id No.: 31708505001
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Upgradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing (Work Pot Patch work started)	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work has been started

(Signature)

NAME: Chetani Kant Singh
DESIGNATION: Junior Engineer

DESIGNATION: Junior Engineer