FIELD INSPECTION REPORT

Date	of Inspection :	6. 12 2020	District: 44. Chem parem		
Division: Narke Dia a. "			Langth (lem): 0 a - 1		
Name	of the Road: Si	nghasam' mm Maintenance	Length (km): 9.300 km		
Scher	ne/Programme:	MAINTENANCE	mer property of the state of th	-	
I MCRO	rge No.:		Road Id No.:		
		The second secon	Ongoing/Completed/Under Maintenance on going		
100000	OF MORENING AS A		/Up gradation/ Maintenance	*	
SI. No.		Parameters to be checked		Remarks	
1.	Payement	Payement			
a) Road Junction				ongoing	
b) Condition of		Surfacing		orgaly	
c)	c) Riding Quality		447	ongoing	
d) Road Camber				ongoing	
e)	e) Whether free from aggregates in case of C		n defects such as visible cracks, exposed f CC Pavement.		
f)			ot (CC Pavement)	MA	
g)		of flank/slope & raincuts if any		NA	
2.	Cross Drains	ige			
a)			e pipe culverts including its painting	s MA	
b)			& Wing walls, Slab in RCC culverts		
c)		on of railings/slab/approach for Bridges		MA	
3.	Road Furnitu	TUNE 17 19 19 19 19 19 19 19 19 19 19 19 19 19			
دمناستان	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
期时	Compliance History				
23201	Status of ATR	s & any others		. -	

Overall Rating

Satisfactory (S)	-8
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Chamebrades Pd DESIGNATION: JE