FIELD INSPECTION REPORT

Date of Inspection: 08.12.2020			District: Madhabani		
Division: Phylogras			Length (km): 0.00		
	the Road:	Swrot: to	Parchmanya Ro.		
	Programme:	MAINTENANCE	Istochinarya Obe	-21	
Package			Road Id No.: 212018	2007	
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is	a case of:	New Connectivity/I	Up gradation/ Maintenance		
SL No.		Parameters to	be checked	Remarks	
1,	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4.	Compliance History				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Gargati Tha DESIGNATION: A.E.

Status of ATR's & any others

08/2/2097 AG