

- on going -

FIELD INSPECTION REPORT


Date of Inspection : 8.12.2020	District: Madhubani
Division : R.W.D (WD) Phulprashasti	Length (km): 2.0 km
Name of the Road: NH-104 Dumara Chowk to Dhatla Tol.	
Scheme/Programme: MAINTENANCE	MR 3654 (old)
Package No.: -	Road Id No.: 31909900818
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U } on going
b)	Condition of Surfacing	S/U }
c)	Riding Quality	S/U }
d)	Road Camber	S/U }
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No provision of CC Yes/No } N/A
f)	Contraction Joints provided or not (CC Pavement)	No provision of PCC Pavement Yes/No }
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U } on going
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U }
c)	Condition of railings/slab/approach for Bridges	S/SRI/U }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓ on going
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

* N/A = Not Applicable


 8.12.2020
 (Signature)

NAME: JITENDRA KUMAR
 DESIGNATION: A-E