

FIELD INSPECTION REPORT

Date of Inspection: 07/12/2020 District: East Champaran
 Division: MoGhani Length (km): 6.90 km
 Name of the Road: Belwatiya To Shyampur
 Scheme Programme: MAINTENANCE (New)
 Package No.: — Road Id No.: —
 Status of the Project: ☒ New/Complete for Maintenance
 Work is a case of: ☒ New Connectivity ☐ Upgradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SRI NA
b)	Condition of Surfacing	SRI NA
c)	Rutting/voids	NA
d)	Road Camber	SRI NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes No NA
g)	Compaction of flank slope & raintents if any	Yes No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI/U NA
c)	Condition of railings/slab approach for Bridges	S SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board km & 20 m stones/Pavement road markings are provided and maintained	Sign board Yes No informatory board provided
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NA

Note - Work not started.


 07/12/20
 (Signature)

NAME: Baidyanath Kumar.

DESIGNATION: J.E