

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: Samastipur
Division : Dabighau		Length (km): 5.3
Name of the Road: R.E.O road - Kisanpur Tabhaka		
Scheme/Programme: MAINTENANCE		MR NEW
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	Stipulated date of Comp. — S/U
b)	Condition of Surfacing	is over but BT work not — S/U
c)	Riding Quality	Has to till now. — S/U
d)	Road Camber	— S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	— S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Work delayed beyond stipulated date.

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME:

Rameel Kumar Singh

DESIGNATION:

g't

(Signature)

04/12/2020