FIELD INSPECTION REPORT

PMUSY-RRP-TT

Date of I	nspection:	05 12 2020	District: 79miu	
			Length (km): 2.5 KM	
Name of	the same of the sa	Dighi-Chattik	hilar pminsy Rd to salve	I Pus. Road
	Programme:	MAINTENANCE		or John Co
Package			Road Id No.: 2080410	1004
		Ongoing/Completed/Under Maintenance		
BACK THE R. W. LEWIS CO.	a case of:		p gradation/ Maintenance	
\$1. No.		Parameters to	be checked	Remarks
	Pavement			7-3
a)	Road Junction condition			SAU
b)	Condition of Surfacing			SAU
c)	Riding Quality			SAF
d)	Road Camber			SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yeshio
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	Be to go to		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance I	fistory		
a)	A COLUMN TO A COLU	's & any others	Charles device 10.00	
	The second second second second			

Overall Rating

Satisfactory (S)	100
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

Executive Engineer RWD Works Division, Jamui

NAME: