

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District:	Tamil.
Division :	Jhatha.	Length (km):	2.22
Name of the Road:	Karangash - Nawada.		
Scheme/Programme:	MAINTENANCE	NMP-2018	
Package No.:	MR-N/19-20/Jhatha/05	Road Id No.:	NEA 22000704
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U H/A
b)	Condition of Surfacing	S/U H/A
c)	Riding Quality	S/U H/A
d)	Road Camber	S/U H/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No H/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H/A
g)	Compaction of flank/slope & raincuts if any	Yes/No In progress
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U H/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Partially.
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

04.12.2020
(Signature)

NAME: Shanker pd. Yadav

DESIGNATION: J.E