

FIELD INSTRUCTION REPORT

Date of Inspection:	10/18/2020	District:	Parkway
Division:	PAVING	Length (mi):	0.231 mi
Name of the Road:	Hwy 28 in front of Parkview Drive		
Schema Program:	MAINTENANCE		
Package No:	11/11/20	Road Id No:	
Status of the Project:	Engineering completed Under Construction		
Work is a case of:	New or Renewal or Upgrades Maintenance		

Work to be done at		Remarks
Sl. No.	Parameters to be checked	
1.	Pavement	
a)	Road from completion	Yes
b)	Condition of Surfacing	Yes
c)	Binding Quality	Yes
d)	Road Number	Yes
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes No
f)	Contraction joints provided or not (CC Pavement)	Yes No
g)	Compaction of flank/slope & raincuts if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SSRIU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSRIU
c)	Condition of railings/slab approach for Bridges	SSRIU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes No
4.	Compliance History	
a)	Status of A/R's & any others	

Overall Rating

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

SAME:

Surrendered 10/1/41

DESIGNATION:

AB Ring Museum

(Signature)