

# FIELD INSPECTION REPORT

Date of Inspection : 09/12/20		District: Jamuzi
Division : Jamuzi		Length (km): 3 km
Name of the Road: Amin To Bakshanpur		
Scheme/Programme: MAINTENANCE		
Package No.: 15RRP-63	Road Id No.: 20804102112	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U ✓
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<del>S/SRI/U</del>
c)	Condition of railings/slab/approach for Bridges	<del>S/SRI/U</del>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

*Aisla*  
09-12-20  
OE

*[Signature]*  
09/12/20  
A-E

(Signature)

NAME:

DESIGNATION: