FIELD INSPECTION REPORT

	spection: O	7/12/20	District: Jamuz'	
Division: Jamuz			Length (km): 1.4 KM	
Name of t	he Road: K	hardin To Ma	npur Harizan Tola	
	rogramme:	MAINTENANCE		
	No.: 15R	A SECTION AND ADMINISTRATION OF THE PARTY OF	Road Id No.: 20 80 410 210	14
	the Project:		d/Under Maintenance	
Work is a			Up gradation/ Maintenance	Consequences and the second
Sl. No.		Parameter (be checked	Remarks
	Pavement		nerone is a selection of the selection o	
a)	Road Junction condition			S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			y€s/No
f)	Contraction Joints provided or not (CC Pavement)			Yés/No
g)	Compaction of flank/slope & raincuts if any			Yes/No/
1 2	Cross Drain	age (4.1.1)		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnit	iure		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/Nø
	i compliance	ffision/		
a)	Status of AT	R's & any others		N/A

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	でいい
Unsatisfactory (U)	Med.

Asigon por lo

A.E.

(Signature)

NAME:

DESIGNATION: