FIELD INSPECTION REPORT

Date of I	nspection : O	alu ba	District: Tamui	
Date of Inspection: 09/12/20			Length (km): 1.750 Km	
	· Jamo	tucsaingan		
	Programme:	MAINTENANCE) 34.34	
	No.: ISR		Road Id No.: 208041021	48
	f the Project:	Ongoing/Completed	/Under Maintenance	
	a case of:	New Connectivity/U	Jp gradation/ Maintenance	
SI No.		Parameters to	pe checked	Remarks
1.	Pavement			
a)	Road Junction	condition		S/U
b)	Condition of Surfacing			S/U/
c)	Riding Quality			. S/U V
d)	Road Camber			√S/U
e)	Whether free	from defects successes of CC Pavement.	h as visible cracks, exposed	Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Cross Drains	SC Inches	The second secon	
a)				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			_S/SRI/UN
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U N
3.	Road Eurnitu	the second second second second	A CONTRACTOR OF THE CONTRACTOR	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
41.774	Complinice	(sió r y)	White was the state of the stat	
a)	Status of ATR	's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	V.

Agizar 20

Arc Indus

(Signature)

NAME:

DESIGNATION: