

# FIELD INSPECTION REPORT

Date of Inspection :	09/12/2020	District:	Jamui
Division :	Jamui	Length (km):	6.50 Km
Name of the Road:	L079-Kohbarba More Katakaba River Road		
Scheme/Programme:	MAINTENANCE	Banjhekusum	
Package No.:	BR-15R-236	Road Id No.:	20804102157
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

1025 to

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	SA
c)	Riding Quality	SA
d)	Road Camber	SA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/SA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/SA
c)	Condition of railings/slab/approach for Bridges	S/SRI/SA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:




(Signature)