

FIELD INSPECTION REPORT

Date of Inspection : 09/12/2020	District: Jamui
Division : Jamui	Length (km): 1.85 Km
Name of the Road: L-115 - Kohbarba Jhaja PWD Road To Ranyang	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 20804102183
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/ No
f)	Contraction Joints provided or not (CC Pavement)	Yes/ No
g)	Compaction of flank/slope & raincuts if any	Yes /No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/ U
c)	Condition of railings/slab/approach for Bridges	S/SRI/ U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/ No
4. Compliance History		
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

(Signature)