

FIELD INSPECTION REPORT

Date of Inspection :	09/12/2020	District:	Jamun
Division :	Jamun	Length (km):	
Name of the Road:	L120 - Kohbarwa Jhalda Road To Ghatari		
Scheme/Programme:	MAINTENANCE		
Package No.:	AR-15R-331	Road Id No.:	20804102186
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	SAJ
b)	Condition of Surfacing	SAJ
c)	Riding Quality	SAJ
d)	Road Camber	SAJ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	YesNo
f)	Contraction Joints provided or not (CC Pavement)	YesNo
g)	Compaction of flank/slope & raincuts if any	YesNo
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YesNo
4	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:



 9/12/20
 AE, Laxmanpur (Signature)