

FIELD INSPECTION REPORT

Date of Inspection:	10/12/2020	District:	Darbhanga
Division:	RWD (W)-Darbhanga-L	Length(Km):	1.377
Name of Road:	L032-T03, Sonki to Purkhotimpur		
Scheme/Programme:	Maintenance ✓		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U <u>S</u>
b)	Condition of Surfacing	S/U <u>S</u>
c)	Riding Quality	S/U <u>S</u>
d)	Road Camber	S/U <u>S</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No <u>No</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>Yes</u>
g)	Compaction of flank /slope & raincuts if any	Yes/No <u>No</u>
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>S</u>
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	N/A S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whethersign boards/ infromatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No <u>Yes</u>
3	Compliance History	
a)	Status of ATR's & any others	<u>No</u>

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	<u>SRI</u>
Unsatisfactory (U)	

550.m. road length is damaged due to consecutive years flood.

Name:

Designation:

10/12/20
OK.

(Signature)

10/12/20
me