FIELD INSPECTION REPORT

		FIELD INSPECTION	REPURI	
Date	of Inspection:	10/12/2020	District:	Darbhaye
Division:		Darbange-1	Length(Km):	1.80
Name of Road:		Daskarga-1 Length(Km): 1.80  Sonke' pwD kalyan chowk to Rasal pur Salula.		
Scheme/Progrmme:		Maintenariee Maintenariee		
		Maintenance	Desdring	
Package No.		Road Id No.		
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/Maintenance		
S No.	No. Parameters to be Checcked			Remarks
1	Pavement			
a)	Road Junction condition			S/U S
b) ·	Condition of Surfacing			S/U S
c)	Riding Quality			S/U ≤
d)	Road Camber			S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)			Yes/No Yes
g)	Compaction of flank /slope & raincuts if any			Yes/No Yes
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			JN/A S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			N/A S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U N/A
3	Road Furniture			
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained			Yes/No
3	Complianace History			
a)	Status of ATR's & any others		No	
)vore!	1 Pating:		<u> </u>	· · · · · · · · · · · · · · · · · · ·
veral	l Rating: Γ	Satisfactory (S)		
		Satisfactory but requires Imp	provement (SRI)	SRI
		Unsatisfactory (U)	,	

الم المراق

Name:

Designation:

(Signature)