

FIELD INSPECTION REPORT

Date of Inspection : 10-12-2020	District: DARBHANGA
Division : DARBHANGA-1	Length (km): 1.920 K.M.
Name of the Road: PRIMARY SCHOOL PARVAM MUKHYA SHAK TO SINGHIA	
Scheme/Programme: MAINTENANCE	
Package No.: 11/A	Road Id No.: 71/8
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	S/U✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No✓
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A.

DALIT BASTI

N/A.

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

Surface Ravelled,
due to flood,
situation keep starting

10/12/20

J.E.

NAME:

(Manohar Lal Ram)

J.E.

DESIGNATION:

10/12/2020

(Signature)

(MANIK PRASAD SINGH)

A.E.