FIELD INSPECTION REPORT

Date of Inspection :	-13 -7020
Division: Dan Lha	District: Day
Name of the Road: To	Length (km): 0.875 km
Scheme/Programme:	MAINTENANCE Hariyan Tola
Package No.:	
Status of the Project:	Ongoing/Completed/V
Work is a case of:	Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance
CI No	Maintenance

Sl. No.	No. Parameters to be checked	
1.	Pavement	Remarks
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U S Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	- Carro
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U _
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	4
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	2

(Signature)

DESIGNATION: A E. natoria