FIELD INSPECTION REPORT

-		FIELD INSPECTION	REPURI	
Date	of Inspection:	10/12/2020	District:	Darbhouse
Division:		Derborge-1	Length(Km):	1.60
Name of Road:		Destacre-1 Length(Km): 1.60 Sonki Rampur chowk to Mehrayi tol a.		
Scheme/Progrmme:		Maintenance		
Package No.			Road Id No.	
Status of the Project:		Ongoing/Completed/ Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/Maintenance		
S No.	No. Parameters to be Checcked			Remarks
1	Pavement			
a)	Road Junction cond	lition S/U <u>C</u>		
b) ·	Condition of Surfacing			S/U ~
c)	Riding Quality			S/U <
d)	Road Camber			S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)			Yes/No Yes
g)	Compaction of flank /slope & raincuts if any			Yes/No No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			N/4 S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			H/A S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U N/L
3	Road Furnityre			
a)	Whethersign boards/informatory/cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained			Yes/No
3	Complianace l	History		
a)	Status of ATR's & any others		No	
200	I Deting			•
veral	l Rating:	Satisfactory (S)		- 1
		Satisfactory (5) Satisfactory but requires Im	provement (SRI)	SPS
	, , , , , , , , , , , , , , , , , , ,	Unsatisfactory (U)		

Name:

Designation:

/Signature