

FIELD INSPECTION REPORT

Date of Inspection : 09/12/2020		District: Banka
Division : Banka		Length (km): 3.630 Km
Name of the Road: Const ⁿ of Road from 2010 S Dada to Chananthera (PMUS (A))		
Scheme/Programme: MAINTENANCE		
Package No.: BR03R452	Road Id No.: 20703602223	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (N/A)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (N/A)
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	(N/A) S/SRI/U
c)	Condition of railings/slab/approach for Bridges	(N/A) S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	'U'

Houy
09/12/2020
(Signature)

NAME: Krishna Kumar Saha

Executive Engineer
RWD, Banka-2