


# FIELD INSPECTION REPORT

Date of Inspection : 09/12/2020	District: Banka
Division : Banka-2	Length (km): 1.800 KM
Name of the Road: Custn of Rd from Laraiya to Adarammusa Rd (NTSNK)	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 20703618015
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	(N/A) S/SRI/U
c)	Condition of railings/slab/approach for Bridges	(N/A) S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

  
 09/12/2020  
 (Signature)

NAME: Kishna Kumar Sinla

EE/RWD  
 Banka-2