FIELD INSPECTION REPORT

Date o	f Inspection: 09/	12/2020	District: Jamus	
Division: Samu'		Length (km): 2.121 Km		
Name	of the Road: Jam	u' khap	afour PWD Range) To S
Schem	e/Programme: MA	INTENANCE	Q1	2009
	ge No.: BR-15 K	2-375	Road Id No.: 2080410	1222
	of the Project: Ong	oing/Completed	/Under Maintenance	
Management .			p gradation/ Maintenance	Remarks
SI No	アイングログログ アード・アーファンストー	iaremoder ui		
7.1	and the second second	THE CHARLES		
a)	Road Junction condition			<i>~</i> 8/U
b)	Condition of Surfacing			-8 /U
c)	Riding Quality			<u>~\$</u> /U
d)	Road Camber			SÆ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes /No-
f)	Contraction Joints provided or not (CC Pavement)			Yes/ No-
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Continued.			
a)	Condition of head walls in Hume pipe culverts including its painting			_S/SRIÆ
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Familiore		Control of the Contro	lar - v es or - s v
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes /No
1	koműlmigyikións		少可以 是一个	
a)	Status of ATR's & any	others	distributed designations	MA

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	584
Unsatisfactory (U)	1

Je Signature)

NAME:

DESIGNATION: