

FIELD INSPECTION REPORT

Date of Inspection : 8/10/20 District : Madhepura
 Division : Madhepura Length (km) : 2.5 (V. H)
 Name of the Road : Exposed Bit. Road Madhepura part under 40 catagory
 Scheme/Programme : MAINTENANCE MP 9.034 (old)
 Package No. : Road ID No.
 Status of the Project : Ongoing/Completed/Under Maintenance
 Work is a case of : New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & rancuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓
c)	Condition of railings/slab/approach for Bridges	✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/1m & 200m stones/Pavement road markings are provided and maintained	✓
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

Birendra Kumar

J.E, Madhepura

NAME:

Birend 8/10/20

(Signature)