## FIELD INSPECTION REPORT

Date of I	nspection :	Die	trict:	
Division :			Length (km):	
Name of	the Road:	WD Roed Colyhur	to Dharamchar Via	ma-Lalar
Scheme/	Programme:	MAINTENANCE	TO DIAYAIIYALVIA	Mas nerms
Package	The second	Ros	nd Id No.:	
	f the Project:	Ongoing/Completed/Und	er Maintenance	
Work is	a case of:	New Connectivity/Up gra	dation/ Maintenance	
Sl. No.	No. Parameters to be checked		Remarks	
1.	Payement			
a)	Road Junction condition			SIU
b)	Condition of Surfacing			SIU
c)	Riding Quality			SIU
d)	Road Camber			VS/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Wes/No
g)	Compaction of flank/slope & raincuts if any			¥€s/No
2.	Cross Drainage			20304
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
41	Compliance History			
a)	Status of ATR's & any others		ND	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Virgod Kurgas Singh

(Signature)

DESIGNATION: