FIELD INSPECTION REPORT

| ate of I | nspection: 65 2 60 | strict: Jamui | 19 |
|---------------|--|---|--|
| lyleion: Take | | ngth (km): 960 m | 4 |
| ame of | the Road: Jamui Lachhuar 4 | prop Path More TO G | unhar Tex |
| heme/ | Programme: MAINTENANCE / N | abard | |
| ckage | No.: No.: Ro | oad Id No.: 20804100 | 325 |
| atus of | the Project: Ongoing/Completed/Uno | der Maintenance | |
| ork is | a case of: New Connectivity/Up gr | adation/ Maintenance | MANAGER MENTERS OF STREET |
| l. No. | A confident with the confidence of the confidenc | ileeked 1 | Remarks |
| 1. | Pavement | | |
| a) | Road Junction condition | | S/U |
| | Condition of Surfacing | | _8/U |
| b) | | | √8/ U |
| c) | Riding Quality | | √8/U |
| d) | Road Camber | s visible cracks, exposed | V-6/No |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | Yes/No |
| 2. | Cross Drainage | ANTA STATE OF THE | |
| | Condition of head walls in Hume pipe culverts including its painting | | S/SRI/U |
| a) | Condition of Abutment & Wing walls, Slab in RCC culverts | | S/SRI/U-N |
| b) | Condition of railings/slab/approach for Bridges | | S/SRI/UN |
| c) | The state of the s | 7.714.00.000 | |
| 3. | Road Parmiture | D 10 - 0 700- | A STATE OF THE STA |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | Yes/No |
| | complimications | | |
| 医 | Status of ATR's & any others | | NA |

| Satisfactory (S) | |
|---|-------|
| Satisfactory but requires Improvement (SRI) | 5.R.I |
| Unsatisfactory (U) | |

DE.

(Signature)

NAME:

DESIGNATION: