## FIELD INSPECTION REPORT

		A REED IN STREET			
Date of Inspection: 09/12/20			District: Jamui		
ivision: Tomui			Length (km): A00 m		
Name of th	ne Road: N	har Read TO P	SirJu Yadar REU Road	ak	
	rogramme:	MAINTENANCE			
ackage N	lo.:		Road Id No.: 2080410183	33	
status of the Project: Ongoing/Comp		Ongoing/Completed	ted/Under Maintenance		
Work is a	case of:	New Connectivity/	Jp gradation/ Maintenance	Dawarke	
SI. No.		Parameters to	pe checked	The state of the s	
11	Pavement	Company of the Carry of the Car			
THE PERSON NAMED IN	Road Junction	n condition		<b>√87</b> U	
a)				✓S/U	
b)	Condition of Surfacing			<b>87</b> U	
c)	Riding Quality			<b>28/</b> U	
d)	Poed Camber				
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yés/No	
g)	Compaction of flank/slope & raincuts if any  Yes/No				
# 15 E	Cross Drai	nage			
	Condition 0	f head walls in Hume	pipe culverts including its painting	S/SRI/U	
a)	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/Ut				
b)	Condition of Abutment & Wing Water,  Condition of railings/slab/approach for Bridges  S/SRI/C			_S/SRI/UN	
c)		The state of the same of the s		Sales and the sa	
3.	Road Forn		Principle of the second	1	
a)	Whether s	ement road markings a	ry/cautionary Board/km & 200m are provided and maintained	Yes/No	
	etik (okon natrii)	dillion Victoria			
a)	Status of A	TR's & any others		1	

Overall Rating

Z

Satisfactory (S)	9
Satisfactory but requires Improvement (SRI)	S. R.I
Unsatisfactory (U)	

Agria 20

A.E. OS 112120

(Signature)

NAME:

DESIGNATION: