FIELD INSPECTION REPORT

			HIOI BC	TON REPORT	
ate	of I	nspection :-	08-12-2020	Dietriot - S - OLing	
DIVISION: PATOXI				District: - Samastipus Length (km): -0.580 kM	
Me	of	the Road: -(:	nu Dta Dandh Se Dxi	un chauzasia Ke Gihaz	11-to 4110
		og: xmme:	MAINTENANCE I	MMGSY (NOB, Poricks)
Package No.: Status of the Project: Ongoing/Complete				Road Id No.: d/Under Maintenance	
SI. N	lo.	2	Parameters to b	cheoked	Remark
L	19.00	Pavement			· .
a)		Road Junction condition			√S/U
b)		Condition of Surfacing			√\$/U
c)		Riding Quality			~8/ U
d)		Road Camber			~/\$/ U
e)		Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-Yes/No
f)		Contraction Joints provided or not (CC Pavement)			Yes/No
g)		Compaction of	of flank/slope & raincuts	if any	Yes/No
2.		Cross Brain	ige (
a)	_/	Condition of l	nead walls in Hume pipe	culverts including its painting	S/SRI/U-
b)		Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/L
2)	10	Condition of re	ailings/slab/approach for	Bridges	S/SRI/U
<u>.</u>	F	Road Furniture			
)			boards/informatory/cau nt road markings are pro	tionary Board/km & 200m	Yos/No
.	C	Compliance History			
)	Si	Status of ATR's & any others		(No any ATR)	N-A
	-				
erall	Rat	ing :	Satisfactory (S)		S
			Satisfactory but requ	nires Improvement (SRI)	
			Unsatisfactory (U)		

NAME: -Ravi Ranjan
DESIGNATION: -J. E