

# FIELD INSPECTION REPORT

Date of Inspection :	07-12-2020	District :	BHAGALPUR
Division :	NAUGACHIA	Length (km) :	2.400 Km
Name of the Road :	R.C.D Road No. 14 TIGASI CHOWK to Saidpur Gopalpur Block in Sukatiya Bazar		
Scheme/Programme :	Maintenance		
Package No. :		Road Id No. :	20703300816
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameteres to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Road Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Conpaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Cross Drainage		
a)	Whether sign boards/informatory/cautionaty Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI.
	Unsatisfactory (U)	

Maintenance Board not fixed. Km post & 200 M Post not maintain. Notice will be issued soon. 07-12-2020.

(Signature)

NAME : ANIL KUMAR

DESIGNATION : ASSISTANT ENGINEER.

R.W.D. WORKS SUBDIVISION GOPALPUR.