FIELD INSPECTION REPORT

Date of Inspection :- 712, 20		District: Wofand	
Division: Khojama		Length (Km):- 0.930	/1 in
Name of Ro	pad:- knofasna Sommank	District:- Moganta Length (Km):- 0.930 Lipup Road to Sanhau Asla	non .
Scheme/Programme :- New MK		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :-		Ongoing/Complete/Under Maintenance	
Work is a	case of: Surface dressis	New Connectivity/Up gradation/ Mainte	nance
Sl. No.	Parameters to be cheeked		Remarks
1.	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surface		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contruction Joints provided or not	t (CC Pavement)	Yes/No
	Compaction of flank/slope & raincuts if any		Yes/No
g) -	Cross Drainage		
	Cross Dramage Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
a)	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U
b)	Condition of Abutment & Wing Wans, Slab in No. 3		S/SRI/U
c)	Condition of railings/slab/approach for bridges		
3.	Road Furniture No. 1 Company Roard /km & 200 m stone /		V /N-
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained Yes/N		Yes/No
4.	Compliance History		1.1
a)	Status of ATR's & any others		11/0.
			5

Overall Rating:

Satisfactory (S)	3
Satisfactory but requires Inprovement (SRI)	
Unsatisfactory (U)	

(Signature) 7.12. 20 5E/Alaul