

FIELD INSPECTION REPORT

Date of Inspection :	06.12.2020	District:	W. Champaran
Division :	Mardaha	Length (km):	5.450 km
Name of the Road:	Rambhura to Bhagata		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	ongoing	S/U
b)	Condition of Surfacing	ongoing	S/U
c)	Riding Quality	ongoing	S/U
d)	Road Camber	ongoing	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA	Yes/No
g)	Compaction of flank/slope & raincuts if any	NA	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	ongoing	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature)
06/12/20

NAME: Chandradeo Pal

DESIGNATION: JE