

FIELD INSPECTION REPORT

Date of Inspection : 09.12.2020		District: 00 Champaran
Division : Narkatiaganj		Length (km):
Name of the Road: Sikta Balthen RD Road to Sikta Village.		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WE/NAR/0015/12	Road Id No.: 318891031228	
Status of the Project: Ongoing/Completed/Under Maintenance	Ongoing	
Work is a case of: New Connectivity/Up gradation/ Main'tenance	Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	Ongoing
c)	Riding Quality	Ongoing
d)	Road Camber	Ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Ongoing
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2.	Cross-Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board stones/Pavement road markings are provided and maintained	Ongoing
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Chandradas Pd
DESIGNATION: JE

(Signature)
09/12/20
JE