FIELD INSPECTION REPORT

Date o	of Inspection: 10.12.20 District: East Cham	District: East Champaran	
Division: Rexact Length (km): 1.655×1			
	of the Road: PHD road road Sripur to Murle		
	ge No.: S Road Id No. 2170510		
named to the	ge No.: S Road Id No.: 3178510 of the Project: Ongoing/Completed/Under Maintenance	32018	
constraint or water	is a case of: New Connectivity/Up gradation/ Maintenance	in a super the colonial ex-	
SI. No	The second secon	Remarks	
1.	Pavement A		
,1)	Road Junction condition	\$/U	
b)	Condition of Surfacing	\$/(1	
c)	Riding Quality , A'	S/U	
d)	Road Camber	S/U	
c)	Whether free from defects such as visible cracks, expose aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its paintin	g S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	Di CHCI (
a)	Whether sign boards/informatory/cautionary Board/km & 200r stones/Pavement road markings are provided and maintained	n Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		
verall R	Satisfactory (S)	(8)	
	Satisfactory but requires Improvement (SRI)	J	
	Unsatisfactory (U)		

Note! - Clearing and pot filling work in progress.

(Signature) 12/20

NAME: Cliffiles & Kumar Ling

DESIGNATION: Junior Engineer, Chayredaho