

FIELD INSPECTION REPORT

Date of Inspection :	District: <i>U. Champaran</i>	
Division : <i>Narhatigang</i>	Length (km): <i>1.575 km</i>	
Name of the Road: <i>Sitalpur to Bisanchi</i>		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>ongoing</i>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>maintenance</i>	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<i>ongoing</i>
b)	Condition of Surfacing	<i>ongoing</i>
c)	Riding Quality	<i>ongoing</i>
d)	Road Camber	<i>ongoing</i>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>ongoing</i>
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	<i>S</i>
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Chandra
(Signature)

NAME: *Chandrales Pd*

DESIGNATION: *JE*