

# FIELD INSPECTION REPORT

Date of Inspection : 08-12-2020	District: East Champaran
Division : Sikharua (Dhaka)	Length (km): 0.99 km
Name of the Road: Purnahiya Tharokhar path to Ghorasahan via B.R.C. Bhawan	
Scheme/Programme: MAINTENANCE (New Maintenance Policy 2018)	
Package No.:	Road Id No.: 317861032258
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : N.A.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*Nand Gopal*  
08/12/2020  
(Signature)

NAME: Nand Gopal.  
DESIGNATION: A.E. R.W.D, Dhaka.