## FIELD INSPECTION REPORT

Date of Inspection :	2-12-2020	District: Nohton		
Division: C.C		Length (km): 1. 20		
Name of the Road:	mru Rama	CE gate to Noho	19	
Scheme/Programme:	MAINTENAN	ĆE –		
Package No.:		Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			
On 51	Paramete	ers to be checked	Remarks	

SI. No.	Parameters to be checked	Remarks	
1.	Pavement	1	
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History	100	
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Note - This Road to Under Tender Pressy

NAME:

Umos

:

DESIGNATION:

New /