SJ. HO-15

FIELD INSPECTION REPORT

Date of Inspection: 08.12-2020 District: Bamastiyer				
Division: Paton'			Length (km):	
Name of	the Road: A	halad chou	ok to Bangra	****
Scheme/	Programme:	MAINTENANCE		-
Package			Road Id No.;	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance Ougoing New Connectivity/Up gradation/ Maintenance MR		
1.	Pavement			
a)	Road Junction	S/U		
b)	Condition of S	S/U		
c)	Riding Quality	S/U		
d)	Road Camber	S/U		
e)	Whether free aggregates in	Yes/No		
f)	Contraction Jo	Yes/No		
g)	Compaction of	Yes/No		
2.	Cross Drains			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started.

NAME: Agy Ks. Singh

DESIGNATION: J. 6

Styr-05/12/2020 A.E 0 8/19/2077 (Signature)