

FIELD INSPECTION REPORT

Date of Inspection :	8/12/20	District:	Madhepura.
Division :	Madhepura	Length (km):	1.20 km
Name of the Road:			
Scheme/Programme:	MAINTENANCE	M R-3054 (New)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross-Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Birendra Kumar
J.E., Madhepura
NAME:

Birendra
8/12/20
J.E.
(Signature)