

FIELD INSPECTION REPORT

Date of Inspection : 09-12-2020	District: Purnea
Division : Bansi	Length (km): 2.740 km
Name of the Road: (1040 Daspur To Ramn. kalam)	
Scheme/Programme:	MAINTENANCE (MR 3054)
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - NA
b)	Condition of Surfacing	S/U - NA
c)	Riding Quality	S/U - NA
d)	Road Camber	S/U - NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - NA
g)	Compaction of flank/slope & raincuts if any	Yes/No - NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	- NA - (Recently work
Satisfactory but requires Improvement (SRI)	has been started).
Unsatisfactory (U)	

haurav kumar
(Signature) 09-12-2020

NAME: GAURAV KUMAR

DESIGNATION: ASSISTANT ENGINEER