## FIELD INSPECTION REPORT

Date of Inspection: 8-12-20		District: Gobagay
Division: LWD G	obalgary-1	Length (km): 370
Name of the Road:	Ahiyabur	to Nivilaha
Scheme/Programme:	MAINTENANCE	
Package No.: MR-N	9-20, G/2-1/14	Road Id No.:
Status of the Project:	Ongoing/Completed	
Work is a case of:	New Connectivity/U	p gradation/ Maintenance

	The Wednied Willy op gradation Maintenance		1
Sl. No.	Parameters to be checked	Remarks	\$
1.	Pavement		L. St. brown
a)	Road Junction condition	S/U W	ork in progre
b)	Condition of Surfacing	S/U W	pork in progre
c)	Riding Quality	S/U h	A
d)	Road Camber	S/U }	JA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	An
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Y	
g)	Compaction of flank/slope & raincuts if any	Yes/No W	orkin progr
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	<del>)n</del>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	1A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	11A
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No §	0%
4.	Compliance History		
a)	Status of ATR's & any others	NO ATR	]

Overall Rating

	74	
Satisfactory (S)	(2)	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

8/13/20 JR 8/12/2000

(Signature)

NAME:

DESIGNATION: