## FIELD INSPECTION REPORT

10 PM	E CONTRACTOR OF THE STATE OF TH	
Date of Inspection : 8	1-19-20	District: Goodgan
Division: RWD (	nopalgay-1	Length (km): 600
Name of the Road:	iswa to Pak	lara Vza Hit Pathi
Scheme/Programme:	MAINTENANCE	
Package No.: MR-H	9-306/07-114	Road Id No.:
Status of the Project:	Ongoing/Completed	/Under Maintenance
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance

Parameters to be checked	Remarks
	是,"一种是对什么,"的
THE PART OF THE PA	s/u (2)
Road Junction condition	
Condition of Surfacing	
Riding Quality	
Road Camber	
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
Contraction Joints provided or not (CC Pavement)	
Compaction of flank/slope & raincuts if any	
e	S/SRI/U (8)
Condition of head walls in Hume pipe culverts including its painting	
Condition of Abutment & Wing walls, Slab in RCC culverts	
Condition of railings/slab/approach for Bridges	
C The state of the	Yes/No 80%
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
是一种的一种,我们就是一种的一种,我们就是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	KIN XITE
Status of ATR's & any others	
	from defects such as visible cracks, exposed use of CC Pavement. Ints provided or not (CC Pavement)  flank/slope & raincuts if any  e  and walls in Hume pipe culverts including its painting butment & Wing walls, Slab in RCC culverts illings/slab/approach for Bridges  re  boards/informatory/cautionary Board/km & 200m are road markings are provided and maintained  istory

Overall Rating

To the Contains (C)	(2)
Satisfactory (S) Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

8/19/90

81,272022

(Signature)

NAME:

**DESIGNATION:**