

New Maintenance Policy.

FIELD INSPECTION REPORT

Date of Inspection : 01/12/2020	District: Gopalgarh
Division : Halki.	Length (km): 1.550 km
Name of the Road: Basu Dhanosh to Mirza Pur.	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U (S)
b)	Condition of Surfacing	S/U (S)
c)	Riding Quality	S/U (S)
d)	Road Camber	S/U (S)
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No - NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (S)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (S)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NOT

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

MANOJ KUMAR

DESIGNATION:

A. E

(Signature)

AB