## FIELD INSPECTION REPORT

narrand

Date of Inspection :		District: \au\ \u'
Division: Wekwh		Length (km):
Name of the Road: C	harahi to i	Lorauna
Scheme/Programme:	MAINTENANCE	
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked		
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History	<del></del>	
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

droped

NAME:

**DESIGNATION:** 

(Signature)