FIELD INSPECTION REPORT

Date of 1	Inspection:	7.12.2020	District: Sitamorahu	
	: RND 8	· torrash	Length (km): 3.040 Cm	
	the Road: B	houro Kothi - Most	ammodpeto-	
Scheme/	Programme:	MAINTENANCE		
		DUDRA	Road Id No.:	
	f the Project:	Ongoing/Completed/		
Work is	a case of:	and the state of the state of the state of	p gradation/ Maintenance	CHARGE TO A POST OF THE
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No			Yes/No
f)	Contraction Joints provided or not (CC Pavement) Yes/N			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance H	listory		
a)	Status of ATR	's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: DINESH PRATAP SINGH

SE

Tender Porcos

NA